10-year Follow-up Meets the Real-World: Expectations and Caveats

Sreekanth Vemulapalli, MD Associate Professor of Medicine Duke University Medical Center

Disclosure of relevant financial relationships

I, Sreekanth Vemulapalli, have the following financial relationships

Grants / Contracts: American College of Cardiology, American Heart Association, National Institutes of Health (R01 and UG3/UH3), Food and Drug Administration, Edwards Lifesciences, Idorsia

Advisory / Consulting: Edwards Lifesciences, Medtronic, Abbott Vascular, Cytokinetics, Astra Zeneca, Haymarket

NOTE: The information, procedural techniques and approaches, content, considerations, and opinions expressed in this content and materials are those of the respective healthcare providers and do not necessarily reflect the opinions, views, or training requirements of Edwards Lifesciences. This content and materials are intended to be an educational resource and for general information only. These content and materials are not intended to replace product training. These materials and content do not constitute medical or business advice or in any way replace the independent medical judgment of a licensed and trained physician with respect to any patient, their needs, or their circumstances. The physician is solely responsible for all decisions and medical judgments relating to the treatment of the patient. Please see the current complete Instructions for Use for products discussed or demonstrated, including all product indications, contraindications, precautions, warnings, and adverse events. The materials are prepared by trained healthcare professionals, who have been using the products or procedures they discuss regularly within their practices, and the use and outcomes may vary.

Disclosure of relevant financial relationships

Within the prior 24 months, I have had a financial relationship with a company producing, marketing, selling, re-selling, or distributing healthcare products used by or on patients:

Grant/Research Support Edwards Lifesciences, Idorsia

Consultant Fees/Honoraria Edwards Lifesciences, Medtronic, Abbott

Vascular, Cytokinetics, Astra Zeneca

Individual Stock(s)/Stock Options None

Royalties/Patent Beneficiary None

Executive Role/Ownership Interest None

Other Financial Benefit None


Outline

- TAVR Evolution, Lifespan, and the Need for 10-year Follow-up
- Practical Difficulties of 10-year follow-up
- Competing Risk of Death
- Missingness at Random and Bias
- Reconsent and Vital Status Sweeps
- A Path Forward: Infrastructure and Consensus Solutions
- Conclusion


The evolution of TAVR




The evolution of TAVR



The evolution of TAVR




Practical difficulties of 10-year follow-up



Practical difficulties of 10-year follow-up



Competing risk of death




Competing risk of death

- 1. Death prevents the observation of non-fatal events / data
- 2. "Missingness" of non-fatal endpoints due to death is unavoidable and likely in TAVR trials due age and comorbidity
- 3. Sensitivity analyses to account for competing risk of death

Missingness at random and bias

Missingness Completely at Random






Missing data points are randomly scattered, so the remaining data is still representative.

Missingness Not at Random

Bias

Missing data depends on the value itself, causing bias in observed data



Missing data depends on the value itself, causing bias


Previous analyses suggest Missingness is non-random

Greater Missingness in:

- Lower QOL
- Surgical Patients
- Older age / frailty
- Distance to site

Reconsent

- Reconsent may be required when study follow-up is extended
- There is no clear guidance on how to obtain reconsent
- Reconsent is an "intercurrent event" that can improve data completeness but can also introduce bias




Vital status sweeps

- Electronic Medical Records Review
- Obituaries
- Next of Kin / PCP / Designated Contact
- Lexis/Nexis
- National Death Index (12–24-month data lag)
- Social Security Death Index
- National Health Databases (not available in US)

Landmark Analysis and missingness in long-term follow-up: PARTNER III 5-year follow-up

Of 95 patients identified, the alive or death status was obtained for 66 patients (N=21 TAVR, N=45 Surgery).



A path forward: endpoint of interest

"The index valve is functioning at 10 years"

Mortality

Valve-Related Mortality

Valve Function

Valve Reintervention / Hemodynamics

A (reusable) path forward

- Consent to linkage at study enrollment
- Data Sources

National Death Index

National Administrative Claims

Administrative Claims

Validated endpoints (death, reintervention)

Electronic Health Records

- Noninvasive Imaging Results
- Procedural Results



Are we there yet?



Data Source	Pros	Cons	Validation State
Administrative Claims	Easy availability	Lacks granularity Doesn't procedural and non- invasive imaging results	Well validated against adjudicated data for Death, Heart Failure Hospitalization, Re-intervention
National Death Index Lexis/Nexis	Definitive national resource on vital status	Lag in Data (12 – 24 months)	Well validated
Electronic Health Records	Granular	Unstructured, difficult data access	Little validation against gold standard (adjudicated data, audited registries)
National Registries	Intermediate granularity	Data Ownership, Data Lag, Decreasing Data Completeness over time	Data is audited, National Coverage Decisions, Previous Adjudication of selected endpoints
Chargemasters	Granular device data with serial numbers	Difficult data access	Little validation against gold standard
Direct to Patient Apps / Patient Reported Data	Mobile, Asynchronous, "Low touch"	Requires upfront consent for contact and alternative contact. Patient burden	Prior Research (Adaptable Trial) suggests Direct to Patient Doesn't Correspond Well to EHR for Hard Outcomes

Conclusions

- The application of TAVR to lower risk and younger patient populations drives the need for 10-year follow-up
- 10-year follow-up is currently burdensome for sponsors, health systems, and patients and is created de novo for each trial
- Burden → non-random missing data → bias
- Completeness of data
 - Reconsent → bias
 - Endpoint of interest: "The index valve is functioning at 10 years"
 - Path forward: Supplement trial data with fit for purpose passive follow-up data
- We still need validation of many data sources

What to watch for in long-term studies

- Endpoints of Interest: Mortality, Re-intervention, Hemodynamics
- Is Competing Risk of Death Appropriately Addressed for Non-Fatal Endpoints?
 - Echos not done due to death do not represent poor trial conduct!
- For True Missing Data is There Any Attempt to Assess for Non-Random Missingness?
- Combating Missingness: Reconsent and Vital Status Sweeps?
- Are There Attempts Made to Account for Missingness?

Important Safety Information

Edwards SAPIEN 3, Edwards SAPIEN 3 Ultra, and Edwards SAPIEN 3 Ultra RESILIA Transcatheter Heart Valve System

Indications: The Edwards SAPIEN 3, SAPIEN 3 Ultra, and SAPIEN 3 Ultra RESILIA Transcatheter Heart Valve system is indicated to reduce the risks associated with progression from asymptomatic to symptomatic severe native calcific aortic stenosis in patients who are judged by a heart team to be appropriate for transcatheter heart valve replacement therapy.

The Edwards SAPIEN 3, SAPIEN 3 Ultra, and SAPIEN 3 Ultra RESILIA Transcatheter Heart Valve system is indicated for relief of aortic stenosis in patients with symptomatic heart disease due to severe native calcific aortic stenosis who are judged by a Heart Team, including a cardiac surgeon, to be appropriate for the transcatheter heart valve replacement therapy.

The Edwards SAPIEN 3, SAPIEN 3 Ultra, and SAPIEN 3 Ultra RESILIA Transcatheter Heart Valve system is indicated for patients with symptomatic heart disease due to a failing (stenosed, insufficient, or combined) surgical or transcatheter bioprosthetic aortic valve, or a native mitral valve with an annuloplasty ring who are judged by a heart team, including a cardiac surgeon, to be at high or greater risk for open surgical therapy (i.e., predicted risk of surgical mortality ≥ 8% at 30 days, based on the Society of Thoracic Surgeons (STS) risk score and other clinical co-morbidities unmeasured by the STS risk calculator).

The Edwards SAPIEN 3, SAPIEN 3 Ultra, and SAPIEN 3 Ultra RESILIA Transcatheter Heart Valve system is indicated for patients with symptomatic heart disease due to a failing (stenosed, insufficient, or combined) surgical bioprosthetic mitral valve who are judged by a heart team, including a cardiac surgeon, to be at intermediate or greater risk for open surgical therapy (i.e., predicted risk of surgical mortality ≥ 4% at 30 days, based on the Society of Thoracic Surgeons (STS) risk score and other clinical co-morbidities unmeasured by the STS risk calculator).

Contraindications: The valves and delivery systems are contraindicated in patients who cannot tolerate an anticoagulation/antiplatelet regimen or who have active bacterial endocarditis or other active infections, or who have significant annuloplasty ring dehiscence.

Warnings: Observation of the pacing lead throughout the procedure is essential to avoid the potential risk of pacing lead perforation. There may be an increased risk of stroke in transcatheter aortic valve replacement procedures, as compared to balloon aortic valvuloplasty or other standard treatments in high or greater risk patients. The devices are designed, intended, and distributed for single use only. Do not resterilize or reuse the devices. There are no data to support the sterility, nonpyrogenicity, and functionality of the devices after reprocessing. Incorrect sizing of the valve may lead to paravalvular leak, migration, embolization, residual gradient (patient-prosthesis mismatch), and/or annular rupture. Accelerated deterioration of the valve due to calcific degeneration may occur in children, adolescents, or young adults and in patients with an altered calcium metabolism. Prior to delivery, the valve must remain hydrated at all times and cannot be exposed to solutions other than its shipping storage solution and sterile physiologic rinsing solution. Valve leaflets mishandled or damaged during any part of the procedure will require replacement of the valve. Caution should be exercised in implanting a valve in patients with clinically significant coronary artery disease. Patients with pre-existing prostheses should be carefully assessed prior to implantation of the valve to ensure proper valve positioning and deployment. Do not use the valve if the tamperevident seal is broken or the storage solution does not completely cover the valve (SAPIEN 3 and SAPIEN 3 Ultra only), the temperature indicator has been activated, the valve is damaged, or the expiration date has elapsed. Do not mishandle the delivery system or use it if the packaging or any components are not sterile, have been opened or are damaged (e.g., kinked or stretched), or if the expiration date has elapsed. Use of excessive contrast media may lead to renal failure. Measure the patient's creatinine level prior to the procedure. Contrast media

Important Safety Information (continued)

except when contraindicated, as determined by their physician. This device has not been tested for use without anticoagulation. Do not add or apply antibiotics to the storage solution (SAPIEN 3 and SAPIEN 3 Ultra only), rinse solution, or to the valve. Balloon valvuloplasty should be avoided in the treatment of failing bioprostheses as this may result in embolization of bioprosthesis material and mechanical disruption of the valve leaflets. Do not perform stand-alone balloon aortic valvuloplasty procedures in the INSPIRIS RESILIA aortic valve for the sizes 19-25 mm. This may expand the valve causing aortic incompetence, coronary embolism or annular rupture. Transcatheter valve replacement in mitral annuloplasty rings is not recommended in cases of partial (incomplete) annuloplasty rings in the absence of annular calcium due to increased risk of valve embolization. Transcatheter valve replacement in mitral annuloplasty rings is not recommended in cases of rigid annuloplasty rings due to increased risk of PVL or THV deformation.

Precautions: Long-term durability has not been established for the valve. Regular medical follow-up is advised to evaluate valve performance. Limited clinical data are available for transcatheter aortic valve replacement in patients with a congenital bicuspid aortic valve who are deemed to be at low surgical risk. Anatomical characteristics should be considered when using the valve in this population. In addition, patient age should be considered as long-term durability of the valve has not been established. Data on TAVR in patients with asymptomatic severe aortic stenosis are based on study of predominantly low surgical risk patients. Limited clinical data to inform benefit-risk considerations are available for TAVR in patients with asymptomatic severe aortic stenosis who are deemed to be at intermediate or greater surgical risk. Glutaraldehyde may cause irritation of the skin, eyes, nose, and throat. Avoid prolonged or repeated exposure to, or breathing of, the solution. Use only with adequate ventilation. If skin contact occurs, immediately flush the affected area with water; in the event of contact with eyes, seek immediate medical attention. For more information about glutaraldehyde exposure, refer to the Safety Data Sheet available from Edwards Lifesciences. If a significant increase in resistance occurs when advancing the catheter through the vasculature, stop advancement and investigate the cause of resistance before proceeding. Do not force passage, as this could increase the risk of vascular complications. As compared to SAPIEN 3, system advancement force may be higher with the use of SAPIEN 3 Ultra/SAPIEN 3 Ultra RESILIA THV in tortuous/challenging vessel anatomies. To maintain proper valve leaflet coaptation, do not overinflate the deployment balloon. Appropriate antibiotic prophylaxis is recommended post-procedure in patients at risk for prosthetic valve infection and endocarditis. Additional precautions for transseptal replacement of a failed mitral valve bioprosthesis include, the presence of devices or thrombus or other abnormalities in the caval vein precluding safe transvenous femoral access for transseptal approach; and the presence of an Atrial Septal Occluder Device or calcium preventing safe transseptal access. Special care must be exercised in mitral valve replacement to avoid entrapment of the subvalvular apparatus. Safety and effectiveness have not been established for patients with the following characteristics/comorbidities: non-calcified aortic annulus; severe ventricular dysfunction with ejection fraction < 20%; congenital unicuspid aortic valve; pre-existing prosthetic ring in the tricuspid position; severe mitral annular calcification (MAC); severe (> 3+) mitral insufficiency, or Gorlin syndrome; blood dyscrasias defined as leukopenia (WBC < 3000 cells/mL), acute anemia (Hb < 9 g/dL), thrombocytopenia (platelet count < 50,000 cells/mL), or history of bleeding diathesis or coagulopathy; hypertrophic cardiomyopathy with or without obstruction (HOCM); echocardiographic evidence of intracardiac mass, thrombus, or vegetation; a known hypersensitivity or contraindication to aspirin, heparin, ticlopidine (Ticlid), or clopidogrel (Plavix), or sensitivity to contrast media, which cannot be adequately premedicated; significant aortic disease, including abdominal aortic or thoracic aneurysm defined as maximal luminal diameter 5 cm or greater, marked tortuosity (hyperacute bend), aortic arch atheroma (especially if thick [> 5 mm], protruding, or ulcerated) or narrowing (especially with calcification and surface irregularities) of the abdominal or thoracic aorta, severe "unfolding" and tortuosity of the thoracic aorta; access characteristics that would preclude safe placement of the Edwards sheath, such as severe obstructive calcification or severe tortuosity; bulky calcified aortic valve leaflets in close proximity to coronary ostia; a concomitant paravalvular leak where the failing prosthesis is not securely fixed in the native annulus or is not structurally intact (e.g., wireform frame fracture, annuloplasty ring dehiscence); or a partially detached leaflet of the failing bioprosthesis that in the aortic position may obstruct a coronary ostium. For Left axillary approach, a left subclavian takeoff angle ~ ≥ 90° from the aortic arch causes sharp angles, which may be responsible for potential sheath kinking, subclavian/axillary dissection and aortic arch damage. For left/right axillary approach, ensure there is flow in Left Internal Mammary Artery (LIMA)/Right Internal Mammary Artery (RIMA) during procedure and monitor pressure in homolateral radial artery. Residual mean gradient may be higher in a "THV-in-failing prosthesis" configuration than that observed following implantation of the valve inside a native aortic annulus using the same size device. Patients with elevated mean gradient post procedure should be carefully followed. It is important that the manufacturer, model and size of the preexisting prosthesis be determined, so that the appropriate valve can be

Important Safety Information (continued)

implanted and a prosthesis-patient mismatch be avoided. Additionally, pre-procedure imaging modalities must be employed to make as accurate a determination of the inner diameter as possible.

Potential Adverse Events: Potential risks associated with the overall procedure, including potential access complications associated with standard cardiac catheterization, balloon valvuloplasty, the potential risks of conscious sedation and/or general anesthesia, and the use of angiography: death; stroke/transient ischemic attack, clusters, or neurological deficit; paralysis; permanent disability; respiratory insufficiency or respiratory failure; hemorrhage requiring transfusion or intervention; cardiovascular injury including perforation or dissection of vessels, ventricle, atrium, septum, myocardium, or valvular structures that may require intervention; pericardial effusion or cardiac tamponade; thoracic bleeding; embolization including air, calcific valve material, or thrombus; infection including septicemia and endocarditis; heart failure; myocardial infarction; renal insufficiency or renal failure; conduction system defect which may require a permanent pacemaker; arrhythmia; retroperitoneal bleed; arteriovenous (AV) fistula or pseudoaneurysm; reoperation; ischemia or nerve injury or brachial plexus injury; restenosis; pulmonary edema; pleural effusion; bleeding; anemia; abnormal lab values (including electrolyte imbalance); hypertension or hypotension; allergic reaction to anesthesia, contrast media, or device materials; hematoma; syncope; pain or changes (e.g., wound infection, hematoma, and other wound care complications) at the access site; exercise intolerance or weakness; inflammation; angina; heart murmur; and fever. Additional potential risks associated with the use of the valve, delivery system, and/or accessories include: cardiac arrest; cardiogenic shock; emergency cardiac surgery; cardiac failure or low cardiac output; coronary flow obstruction/transvalvular flow disturbance; device thrombosis requiring intervention; valve thrombosis; device embolization; device migration or malposition requiring intervention; left ventricular outflow tract obstruction, valve deployment in unintended location; v

Thank you

Important Safety Information (continued)

Edwards Crimper

Indications: The Edwards crimper is indicated for use in preparing the Edwards SAPIEN 3 transcatheter heart valve, Edwards SAPIEN 3 Ultra transcatheter heart valve, and the Edwards SAPIEN 3 Ultra RESILIA transcatheter heart valve for implantation.

Contraindications: There are no known contraindications.

Warnings: The device is designed, intended, and distributed for single use only. Do not resterilize or reuse the device. There are no data to support the sterility, nonpyrogenicity, and functionality of the device after reprocessing. Do not mishandle the device. Do not use the device if the packaging or any components are not sterile, have been opened or are damaged, or the expiration date has elapsed.

Precautions: For special considerations associated with the use of the Edwards crimper prior to THV implantation, refer to the THV Instructions for Use.

Potential Adverse Events: There are no known potential adverse events associated with the Edwards crimper.

CAUTION: Federal (United States) law restricts these devices to sale by or on the order of a physician.

Edwards, Edwards Lifesciences, the stylized E logo, Edwards SAPIEN, Edwards SAPIEN 3, Edwards SAPIEN 3 Ultra, INSPIRIS, INSPIRIS RESILIA, PARTNER, PARTNER II, PARTNER 3, RESILIA, SAPIEN, SAPIEN 3, and SAPIEN 3 Ultra are trademarks pr service marks of Edwards Lifesciences Corporation or its affiliates. All other trademarks are the property of their respective owners.



